



## 2016 Trend Performance Products Jobber Lifter Price Guide

Premium Series			Elite Series		
GM/Chevrolet			GM/Chevrolet		
EC842GM-1	Economy .842 Diameter	\$17.11	LM842GM-1	Late Model .842 Diameter	\$36.53
EC842GM-1H	Economy .842 Diameter - No Oil Hole, Low Movement	\$21.68	LM842GM-1C	Late Model .842 Diameter - DLC Coating	\$82.18
EC842GM-2	Economy .842 Diameter - Oil Hole in Foot	\$20.54	LM842GM-1H	Late Model .842 Diameter - Low Movement Seat Assist	\$41.09
EC842GM-2H	Economy .842 Diameter - Oil Hole in Foot, Low Movement	\$25.11	LM842GM-2	Late Model .842 Diameter - Oil Hole in Foot	\$39.95
Ford			Ford		
EC875FF-1	Economy .875 Diameter	\$17.11	LM842GM-2H	Late Model .842 Diameter - Oil Hole in Foot, Low Movement	\$44.52
EC875FF-1H	Economy .875 Diameter - No Oil Hole, Low Movement	\$21.68	Ford		
EC875FF-2	Economy .875 Diameter - Oil Hole in Foot	\$20.54	LM875F-1	Late Model .875 Diameter	\$36.53
EC875FF-2H	Economy .875 Diameter - Oil Hole in Foot, Low Movement	\$25.11	LM875F-1C	Late Model .875 Diameter - DLC Coating	\$82.18
Mopar/Chrysler			LM875F-1H	Late Model .875 Diameter - Low Movement Seat Assist	\$41.09
EC904CH-1	Economy .904 Diameter	\$17.11	LM875F-2	Late Model .875 Diameter - Oil Hole in Foot, Low Movement	\$39.95
EC904CH-1H	Economy .904 Diameter - No Oil Hole, Low Movement	\$21.68	LM875F-2H	Late Model .875 Diameter - Oil Hole in Foot, Low Movement	\$44.52
EC904CH-2	Economy .904 Diameter - Oil Hole in Foot	\$20.54	Mopar/Chrysler		
EC904CH-2H	Economy .904 Diameter - Oil Hole in Foot, Low Movement	\$25.11	LM904CH-1	Late Model .904 Diameter	\$36.53
			LM904CH-1C	Late Model .904 Diameter - DLC Coating	\$82.18
			LM904CH-1H	Late Model .904 Diameter - Low Movement Seat Assist	\$41.09
			LM904CH-2	Late Model .904 Diameter - Oil Hole in Foot	\$39.95
			LM904CH-2H	Late Model .904 Diameter - Oil Hole in Foot, Low Movement	\$44.52